

# POWDER COATING EQUIPMENT





## Pulse Coating System, KCI-201

Pulse coating reduces coating material consumption by 20 % to bring about the enhancement of coating quality.

### → Summary of Pulse Coating

The existing corona coating was difficult to coat a corner or recessed place with powder charged with a high current because of electrostatic repulsion. In an attempt to resolve such a problem, if you lower voltage and charge powder with a low current, it leads to weaken electrostatic force to cause powder to run down.

What is required to resolve those problems above is to charge powder with a low current and a high voltage, which makes it possible to resolve through the new pulse coating such problems that the existing corona coating style failed.

### → What is Pulse Coating?

Pulse coating is a great and new style of powder coating that repeatedly charges powder with a low current and a high voltage at intervals of short time (15 ~ 30 clock per second)



## All Customers in the World are Satisfied with KCI Products and Services.

### → Merits of Pulse Coating

#### 1. Enhancement of Coating Quality

The existing style of corona coating generally forms an approximate 50 ~ 90  $\mu\text{m}$  of film, while a new style of pulse coating does a relatively regular coating thickness of 40 ~ 70  $\mu\text{m}$ , contributing to the enhancement of coating quality.

#### 2. Reduction in Coating Material Consumption

Pulse coating could form a relatively regular thickness of coating film (70 $\mu\text{m}$  for corona coating and 50 $\mu\text{m}$  for pulse coating in average thickness) compared with the existing corona coating, which leads to reduce coating material consumption by approximately 20 %.

#### 3. Effective Coating for Recessed Places

While powder charged with a high voltage is sprayed to reach recessed places of targets, it is considerably weakened in electrostatic force. Pulse coating can resolve this problem by repeatedly recharging powder, enabling those recessed places to be coated.

#### 4. Effective Recoating

To charge powder with a low current and a high voltage, which is one of the merits of pulse coating, makes it easier to do recoating without a separate control of voltage or current.

#### 5. Decrease in Orange Peel

Pulse coating can significantly decrease orange peel, which is generally caused by a thick powder coating, since it provides more thinner coating than the existing corona style does.



**WARNING**

➔ **INSTALLATION**

- ▶ Properly ground all equipment in the spray area to an earth ground and maintain this ground.
- ▶ Remove all containers of volatiles from the spray area.
- ▶ Establish and maintain a grounded area for the spray operator.
- ▶ The Gun of KCI-200 Series must be connect to KCI-201 Control unit.

➔ **HANDLING**

- ▶ Do not puncture or roughly handle the containers of powder.  
If the contents are scattered, powder may contaminate the air inhaled by operators.

➔ **OPERATION**

- ▶ The operator should hold the gun in his bare hand.  
If gloves are worn, the palm should be out to assure skin-to-metal contact.
- ▶ The operator should wear shoes with conductive shoes, e. g., leather.  
Rubber shoes are not conductive.
- ▶ Ground the tip of the gun before cleaning or changing nozzles.  
when the gun is not in use, it should be hung so that the nozzle is within four inches of a grounded conductor.
- ▶ The operator should wear a filter-type respirator anytime he is exposed to dusty conditions.
- ▶ High pressure powder may cause injury, Keep the rear switch "OFF" position in no-use condition

➔ **MAINTENANCE**

- ▶ Make a periodic confirmation of grounding to earth of all equipment in the spray area.
- ▶ Exercise good housekeeping practices, do not allow dirt or powder to accumulate on the feeder/powder unit, cable, or gun.
- ▶ Keep the cabinet door closed, wipe with a clean dry cloth or with clean, dry air the prevent powder build-up.
- ▶ In case of powder such as spraying paint, dust density of 10g/m<sup>3</sup> or more could cause explosion, and the internal booth should be maintained in good and clean condition.

➔ **PERSONNEL**

- ▶ Use soap and water to remove powder from the skin washing with solvents can cause reactions resulting in allergies and disorders.
- ▶ Wash hands before eating and smoking.
- ▶ Do not use compressed air to blow powder off the hands and clothing.  
This practice may result in damage to the ear drums or eyes.

# KCI Powder Electrostatic Coating Machine Manual Book for Model 201, 203, 204, 206, 207

## CONTENTS

1. POWDER COATING SYSTEM .....	4
2. INSTALLATION .....	28
3. OPERATION .....	30
4. TROUBLE SHOOTING .....	37
5. APPENDIX .....	39



### 1. POWDER COATING UNIT TYPE



● KCI-201 : Manual Spray(Standard Model)



● KCI-206 : Hopperless type  
(Vibrating Plate instead of Powder Container)



● KCI-203 : GUN & Control Unit with  
Mini Hopper (4 l )



● KCI-207 : Auto Gun & Control Unit



● KCI-204 : 204 Cup Gun and Control Unit  
usually for Laboratory

### → APPLICATION

The equipments are designed to be suitable especially for conveyor line or hand job conducted in manual booth.

### POWDER COATING UNIT TYPE 201, 203, 204, 206, 207

#### → FUNCTIONS

- ▶ The fluidized powder in the powder hopper is sucked up in the injector by the conveying air. Through the powder hose the powder/air mixture reaches the gun.
- ▶ The powder is electrostatically charged immediately it reaches the gun nozzle. An intense field also exists between the gun nozzle and the grounded workpiece. The electrostatically charged powder sprayed onto the workpiece adheres to the latter's surfaces.
- ▶ This line voltage is converted in the control module to high-frequency current. This current is stepped up by the high-voltage transformer and the HV-cascade in the gun to -100kV and applied to the electrodes.
- ▶ The conveying air and the dosing air is to be regulated on the control module, the fluidizing air on the pneumatic unit.
- ▶ The powder is fluidized by forcing air from below through a porous plastic plate. The fluidized powder gets liquid-like properties.

#### → Technical data

##### ▶ Power

Single-phase range	220VAC
Frequency	50/60HZ
Type	201,203,204,206,207
Temperature range in use	-10°C+50°C

##### ▶ Powder GUN

Length of Gun	330mm
Gun weight	420g
Rated output voltage	24VDC
Input voltage	- 100kV
Maximum output current	180µA(MAX.)
Maximum powder injection	600g/min
Polarity	negative(-)


##### ▶ Pneumatic technical spec

Maximum input-air pressure	8 kg/cm
Optimum input-air pressure	6 kg/cm
Minimum input-air pressure	4 kg/cm
Maximum water vapor content or compressed Air	1.4g/Nm <sup>3</sup>
Maximum oil vapor content of compressed air	0.1ppm
Maximum compressed-air Consumption	13.2Nm <sup>3</sup> /h

▶ KCI 201 [ Net weight: 37kg Size(WxLxH) : 480x550x950mm ]




POWDER COATING UNIT TYPE 201, 207




- 1. Control Unit
- 2. Spray Gun
- 3. Auto Spray Gun
- 4. Injector
- 5. Regulator
- 6. Powder Hopper
- 7. Gun Hanger
- 8. Trolley

KCI-201 Drawing of Connection



- 1. Manual Gun
- 2. Gun Cable
- 3. Powder Hose
- 4. Auxiliary Air (0.5kg/cm)
- 5. Earth
- 6. Conveying Air
- 7. Dosing Air
- 8. Fluidizing Air (0.4kg/cm)
- 9. Main Air input (6kg/cm)
- 10. Fluidizing Air Regulator(0.4kg/cm)
- 11. Main Air Regulator(6kg/cm)

CONTROL UNIT KCI-201, 203, 204, 205, 206, 207 -A-




PARTS LIST -A-

Control Unit for type 201,203,204,206,207

Drawing No.	Part No.	Unit	Q'ty	Description	Specification
1	2201	EA	1	Solenoid Valve	DC 24V
2	2102	EA	1	Transformer	AC 230V (7v, 0v, 7v, 21v)
3	2103	EA	1	DISPLAY P.C.B	142×45×1.6t
4	2104	EA	1	SUB P.C.B	87×80×1.6t
5	2105	EA	1	MAIN P.C.B	160×92×1.6t
6	2131	EA	1	Power Switch	AC 220/5A
7	2132	EA	1	Hi-Voltage volume knob	φ25 5kΩ
8	2133	EA	1	Select Switch	kV, uA, gun
9	2136	EA	1	Auxiliary air Regulator	inlet 10kg/cm outlet 4kg/cm
10	2135	EA	1	Dosing air Regulator	inlet 10kg/cm outlet 4kg/cm
11	2134	EA	1	Conveying air Regulator	inlet 10kg/cm outlet 6kg/cm
12	2137	EA	1	Pulse Switch	Corona, Pulse (kV, uA)
13	2138	EA	1	Display	Corona, Pulse
14	2141	EA	1	Auxiliary air Manometer	φ41 4kg/cm
15	2140	EA	1	Dosing air Manometer	φ41 4kg/cm
16	2139	EA	1	Conveying air Manometer	φ41 6kg/cm
17	2161	EA	1	Main air one touch nipple	φ8×φ6
18	2162	EA	1	Conveying air nipple	φ8×φ6
19	2163	EA	1	Dosing air nipple	φ6×φ4
20	2164	EA	1	Auxiliary air nipple	φ5×φ3
21	2165	EA	1	Main power cable socket	0.5A 230Vac
22	2166	EA	1	Fuse holder with fuse 3A	3A
23	2167	EA	2	Fuse holder with fuse 1A	1A
24	2168	EA	1	Gun cable socket 5pins	5Pins(MG201)
25	2169	EA	1	Ground nut	M6



MANUAL GUN 201 -B-



PARTS LIST -B-

KCI-201/Manual Spray Gun 201

Drawing No.	Part No.	Unit	Q' ty	Description	Specification
1	2201	EA	1	High- Voltage pack	227×31×35
2	2202	EA	1	Powder Channel(A)	φ15.6×113
3	2203	EA	1	Auxiliary Channel(A)	φ6×110
4	2204	EA	1	Channel bracket	63×31×20
5	2205	EA	1	Auxiliary Channel(B)	φ6×114
6	2206	EA	1	Powder Channel(B)	φ14.6×120
7	2207	EA	1	Auxiliary air nipple	
8	2208	EA	1	Channel holder	φ17.6×36
9	2209	EA	1	Powder hose nipple	φ16×45
9-1	2239	M	1	Powder hose	4.5M
10	2210	EA	1	Cable bracket	14×53
11	2211	EA	1	Gun Cable with connector	φ6×4.5M
12	2213-1	EA	1	Deflector(Small)	φ19
	2213-2	EA	1	Deflector(Medium)	φ24
	2213-3	EA	1	Deflector(Large)	φ32
13	2234	EA	1	Gun Cap	
14	2214	EA	1	Gun Muzzle	φ30×49.5
15	2216	EA	1	Rod	φ8×60
16	2218	EA	1	Rod holder with spring	φ31×48.5
17	2221	EA	1	Gun trigger	12×35×11
18	2223	EA	1	Gun switch	20×6.5×11
19	2235	EA	1	Gun body	260mm
20	2236	EA	1	Hook	
21	2237	EA	1	Gun Handle	
22	2238	EA	1	Gun Back Cover	



Assembled

KCI-201 Manual Gun



Disassembled

High Voltage Generator



Disassembled

front of Gun




# KCI POWDER COATING EQUIPMENT







**AUTO GUN TYPE 207 -C-**




**PARTS LIST -C-**

**KCI-207/Auto Spray Gun 207**

Drawing No.	Part No.	Unit	Q'ty	Description	Specification
1	2701	EA	1	Gun Cap	φ44×62
2	2702	EA	1	Gun Body	260mm
3	2703	EA	1	Hook	
4	2704	EA	1	Gun Bracket	35×120×8
5	2705-1	EA	1	Deflector(Small)	φ19
	2705-2	EA	1	Deflector(Medium)	φ24
	2705-3	EA	1	Deflector(Large)	φ32
6	2706	EA	1	Gun muzzle	φ30×49.5
7	2707	EA	1	Rod	φ8×60
8	2708	EA	1	Rod holder	φ31×48.5
9	2709	EA	1	Powder channel	
10	2710	EA	1	Auxiliary channel	
11	2711	EA	1	Gun cable Jack	
12	2712	EA	1	Powder hose nipple	φ16×45
13	2713	EA	1	Auxiliary air nipple	8×35
14	2755	EA	1	Gun switch	250V/1A
15	2751	M	1	Gun cable with connector	4P×8m
16	2752	M	1	High - Voltage Pack	227×31×35



**POWDER HOPPERLESS 206 -D-**



**PARTS LIST -D-**

KCI-206 Hopperless Sprayer

Drawing No.	Part No.	Unit	Q' ty	Description	Specification
1	400	SET	1	Injector Unit	
2	2632	EA	1	Injector holder	
3	2631	EA	1	Stand arm	
4-1	2630-1	EA	1	Injector powder pipe	
4-2	2630-2	EA	1	Injector air pipe	
5	2609	EA	1	Powder box plate	
6	2629	EA	1	Vibrator switch	
7	2621	EA	1	Main air regulator	
8	2607	EA	1	Fluidizing air regulator	
9	2628	EA	1	Air filter	
10	2624	EA	1	Fluidizing pocket	
11	2625	EA	1	Plate spring	
12	2626	EA	1	Trolley	
13	2610	EA	1	Vibrator	



### → How to use KCI-206(HOPPERLESS)

- ▶ The operating way of KCI-206 control unit is same with KCI-201 basically.  
But KCI-206 do not need hopper but using vibrator to fluidize powder.

### → Operating

- ① Turn regulator which control vibrator air clock wise in order to getting up
- ② Then vibrator start to working the powder box would be vibrating and fluidizing powder.
- ③ Turn powder auxiliary air regulator to clock wise slightly to fluidizing powder.
- ④ Turn the Conveying air regulator.
- ⑤ Others are same with KCI-201 operation.


# KCI

## POWDER COATING EQUIPMENT





**INJECTOR -E-**



**PARTS LIST -E-**

Injector Unit

Drawing No.	Part No.	Unit	Q' ty	Description	Specification
1	401	EA	1	Injector body	64×40×20
2	405	EA	1	Sleeve holder	φ20×48
3	440	EA	1	Insert Sleeve	φ9.8×80
4	415	EA	1	Injector nozzle	28.5× φ1.8
5	410	EA	1	Conveying air one touch fitting	PL 1/8×φ8
6	430	EA	1	Dosing air one touch fitting	PL 1/8×φ6
7	425	EA	1	Check valve	1/8, V18
8	420	EA	1	Check valve bolt	PT 1/8
9	446	EA	1	O-Ring	φ16×1.8t
10	445	EA	1	O-Ring	φ13×1.8t
11	400	Unit	1	Injector Unit	



## INJECTOR -E-



Injector & Injector Pipe



Disassembled Injector

# KCI

## POWDER COATING EQUIPMENT

### → The principle of injector and influence of injected air flowing through injector nozzle create vacuum


- ▶ The vacuum provides the suction powder for getting powder into suction tube, in which the air and powder are mixed.
- ▶ The mixing density of air and powder, as well as powder-extraction amount depend on factors such as injected air, dosing air, powder quality, the length and diameter of powder hose, the height difference between GUN and injector, and the type of hoses.
- ▶ Pressure gauge indicates the operating pressure.
- ▶ Lowering the level of air pressure decrease the output amount of the powder. To implement this, DOSING AIR should take the role of secondary air, which should be injected turn.
- ▶ Increasing DOSING AIR decreases the amount of powder output, and accelerates the speed of injected air.
- ▶ CONVEYING AIR is measured by "BAR" unit.
- ▶ The pressure gauge of DOSING AIR dose not indicate pressure but has something to do with the output amount of paint.





**PNEUMATIC INPUT UNIT -F-**

**PARTS LIST -F-**




**Regulator Unit**

Drawing No.	Part No.	Unit	Q' ty	Description	Specification
1	450	EA	1	Main air coupler	
2	455	EA	1	Pressure reducing valve	3/8x3/8
3	496	EA	1	One-touch fitting	PL 3/8x10φ
4-1	460	EA	1	Main manometer	φ47 10kg/cm
4-2	495	EA	1	Fluidizing manometer	φ47 2kg/cm
5	494	EA	1	One-touch fitting	PL 1/4x10φ
6	486	EA	1	Main air Regulator	
7	480	EA	1	One-touch fitting	PST 1/4x8φ
8	490	EA	1	One-touch fitting	PL 1/4x8φ
9	485	EA	1	Fluidizing air Regulator	
10	491	EA	1	One-touch fitting	PL 1/4x6φ
11	492	EA	1	One-touch fitting	PCF 1/8x6φ
12	493	EA	1	One-touch fitting	PL 1/8x6φ



**POWDER HOPPER -G-**

**PARTS LIST -G-**



**Powder Hopper(40 Liter) Unit**

Drawing No.	Part No.	Unit	Q' ty	Description	Specification
1	355	EA	1	Fluidzing one-touch fitting	PL 1/8 x φ6
2	315	EA	1	Fluiding Plate	φ400×10T
3	301	EA	1	Hopper Body	φ370×500H
4	320	EA	1	Snap Lock	φ400
5	330	EA	1	Vent	φ30×70H
6	335	EA	1	Powder Vent Hose	φ30
7	325	EA	1	Rubber Lid	φ230
8	305	EA	1	Hopper Cover	φ410×15H
9	340	EA	1	Injector Holder	φ45×15H
10	310	EA	1	Hopper bottom case	φ370×50H
11	313	EA	1	Rubber gasket	φ400×10H
12	314	EA	1	Rubber Packing	φ400×15H
13	315	EA	1	Injector Pipe	φ22×L470

## 2. INSTALLATION

### → TYPE KCI-201

- ▶ By default, the powder equipment are shipped as assembled by factory.
- ▶ The complete status of assembly is shown in the illustration of figure KCI-201,206.
- ▶ The support for GUN is installed at the left or right sides of control box.
- ▶ Connects the control box's MAIN AIR(A-17) to MAIN AIR(REGULATOR, F7) output unit with air hose 8φ.
- ▶ Connects the control box's DOSING AIR(A-19) to INJECTOR(E-6) with air hose 6φ
- ▶ Connects the FLUIDIZING AIR(REGULATOR) output unit to HOPPER(G-1) with air hose 6φ.
- ▶ Connects the control box's AUXILIARY AIR(A-20) to GUN(B-7) with air hose 5φ
- ▶ Connects the POWDER HOSE to INJECTOR
- ▶ Connects the GUN CABLE(B-11) to CONTROL BOX(A-24) with air hose 5φ.
- ▶ Connects ground connection cable from ground nut(A-25) to the booth and trolley.
- ▶ Connect main power cable to AC 230V.



Assembled(Front side)



Assembled(Rear side)



Assembled(Injector & Hopper)



Assembled(Air regulator)



Installation



Connecting the Venting Hose



Assembled(Gun & control unit)



Fully Assembled





### 3. OPERATION

#### ➔ PREPARATION FOR TEST OPERATION

##### A. Adjustment for voltage selection

- ▶ All the shipped equipments are fixed at 220V.

##### B. Connection of air supply

- ▶ Coupler : 1/4" pneumatic coupler is used.
- ▶ Compressed air must not contain any oil or moisture.
- ▶ It should be noticed that the oil and moisture contained in the compressed air. Must be filtered out.
- ※ The fluidified air must be locked in until all connections are completed.

##### C. Connection outlet hose

- ▶ Connect the hose by pressing it into the hopper's outlet-hose coupling hole.
- ▶ Place the opposite end of the hose within booth.
- ※ Caution : Atmospheric pressure should be present in the hopper during operation of the equipment.

##### D. Connect ground line.

- ▶ The ground line should be connected to booth or conveyor with a clip.

##### E. Safety regulations

- ① Operator should always take precaution to get grounded to the powder electrostatic machine's GUN handle by marking hold in his/her gloves. He/She should also make it a rule to put on a pair of grounded shoes.
- ② The floor of workplace should be conducted.
- ③ All conducting materials within 5 meters around powder booth are completely grounded.
- ④ Face the GUN to the direction of BOOTH and not to the human body.
- ⑤ In case of powder such as spraying paint, dust density of 10g/m<sup>3</sup> or more could cause explosion, and the internal booth should be maintained in good and clean condition.

#### ➔ CHECKING FUNCTION OPERATION

##### A. Functions

1. Cuts off the powder supply from pressure-decrease valve.
2. Lowers the control box's high-voltage adjustment handle down to bottom-left position.
3. See what happens when the high-voltage adjustment handle is turned from left to right to slowly increase the voltage level.
4. Approach the ground up to the distance of 20cm holding GUN and see the high-voltage display drop.
5. Pull the GUN's trigger.
  - ▶ The high-voltage indicator begins to operate.
  - ▶ Check if the voltage level changes when the high-voltage adjustment handle is turned.
6. Open MAIN AIR and supply air.
7. Pull the GUN's trigger and open the CONVEYING AIR.
  - ▶ The pressure gauge's hand moves.
8. Pull the GUN's trigger close the CONVEYING AIR, and open the DOSING AIR.
  - ▶ The gauge's hand moves.

- ♣ If all factors suggested above is alright, everything is O.K.
  - ▶ Remove powder from the nozzle of gun by auxiliary air.
  - ▶ Power supply and fluidizing air supply.

##### B. Loading

1. Open the lid.
2. Fill powder up to the hopper's handle level.
3. Close the lid and assemble hose.

- ♣ If everything checks alright, the equipment is ready.  
Slightest abnormality requires preferring to the emergency-measure guide.



## ➔ TEST OPERATION

### A. Painting

※ CAUTION : Check if all the conducting materials within 5 meters around powder booth are completely grounded.

1. Check if the powder is fluidified.
2. Turn on the powder switch.
3. Face the GUN to the direction of BOOTH.
4. Pull the trigger.
5. Adjust the high voltage to the required level – The level can Be monitored by a meter.
6. Wait until the first–sprayed powder comes out completely dried.
7. Proceed with spraying object to be powder coated..

### B. Taking stop spraying measure

1. Release the GUN's trigger.
2. Turn off the power switch.  
As the powder is still fluid, you shouldn't adjust the amount of high voltage, cleaning air and powder output.
3. Be sure to turn off the power switch and cut off air valve during lunch time or after finishing work.

### C. Cleaning the powder hose

※ CAUTION : In case of prolonged unuse of equipment, the powder remaining in hose should be eliminated as follows.

1. Take out injector's hose coupling part from the hopper.
2. Turn the GUN to the direction of BOOTH.
3. Attach the AIR GUN tightly to the hose entrance and blow into it.
4. Reassemble it.

## ➔ FLUIDIZING POWDER

### A. Fluidizing powder

The fluid state of powder is closely related to powder type, water content of compressed air and outer temperature.

The fluidizing proceeds independently of control functions.

1. Keep the hopper's lid open.
2. Slowly increase the fluidizing AIR–The powder begins th boil mildly. AIR in the hopper, and adjust to the minimum amount of AIR for uniform boiling.
3. Close the lid.

### B. The amount of powder output and control

The amount powder output is determined by powder type, the length and diameter of hose, and the amount of CONVEYING AIR and DOSING AIR.

1. Check if the powder is normally fluidized.
2. Turn on the power switch.
3. Pull the trigger with the GUN facing to the direction to BOOTH.
4. Open the CONVEYING AIR.
5. Adjust the DOSING AIR  
Turn slowly regulator of dosing air to clock wise form maximum counter clock wise pulling trigger until powder puffing is getting to normal injection.

### C. Control

- Circular : The nozzle is replaceable and available in diameter of  $\phi$ 19,24,32 finishing work.
- Flat : The nozzle is available in diameter finishing work.



## ➔ COLOR CHANGE

### A. Changing powder color

1. Clean the outlet hose hopper completely.
2. Blow into the powder hose with compressed air.
3. Clean the GUN.
4. Put the powder to be used into hopper and finish all the preparation jobs.
5. Turn and spray the GUN toward BOOTH momentarily before the work begins.

### B. How to manage

Routine maintenance of equipment prolongs product life and keeps its performance uniform.

1. Daily check
  - INJECTOR cleaning and INSERT SLEEVE worn-down
  - POWDER HOSE cleaning
  - GUN cleaning
2. Weekly check
  - Cleans the hopper, injector and GUN
  - Powder shouldn't be put in the hopper just before work.
  - Check the ground line between CONTROL BOX, BOOTH, and CONVEYOR.
  - After checking air dehydrator, any water in it should be removed. The air, but for checking the presence of moisture in it.

### C. Checking for shutdown lasting 2-3 days

1. Turn off the Power switch.
2. Clean the CONTROL BOX.
3. Remove the input air and put it away.
4. Check above B-1. Daily check.
5. Remove powder from HOPPER.

## ➔ CLEANING

### A. Hopper

1. Remove fluidizing AIR LINE.
  2. Remove injector.
  3. Take out suction pipe.
  4. Wipe the electric line, AIR HOSE, and powder hose cleanly with cloth.
  5. Wipe the suction pipe clean.
  6. Empty the remaining powder from hopper.
  7. Clean the hopper's inner wall, especially the bottom part, with vacuum cleaner.
  8. Wipe the hopper's inner surface with clean cloth.
  9. Replace the hopper to the original position.
- ※ CAUTION : The hopper must not be filled with powder until work begins..  
Above all, the hopper's inner surface must not be cleaned with thinner or water.

### B. Manual Powder Electrostatic GUN

Routine cleaning of GUN ensures trouble-free operation and normal function at all times.

#### \* Daily cleaning

1. Remove the powder hose from GUN.
2. Remove nozzle from GUN and clean it.
3. Clean the GUN's powder outlet with AIR along the direction of its flow.
4. Clean the GUN's body with AIR.
5. Assemble it.



### C. Spray Nozzle

- \* Daily cleaning
  - Clean the outer surface of nozzle with compressed air. (Don't use thinner or other liquid for cleaning)
  - Clean the nozzle's inside with compressed air after removing it. The powder accumulated in the GUN must be removed.
  - Check if the nozzle is worn down. (replace it after checking)
  - Check if the compressed air's oil and moisture are completely removed.

### D. Injector

1. Disconnecting powder Hose.
2. Remove Sleeve Holder.
3. Clean Sleeve and inside of Injector Body.


## 4. TROUBLE SHOOTING

MALFUNCTION	CAUSE	MEASURE
High-voltage display does not operate even after powder is on and trigger is pulled.	<ul style="list-style-type: none"> <li>• Electric faulty–The electric line coming into CONTROL BOX is not properly connected.</li> <li>• Faulty fuse and bad equipment</li> <li>• Faulty fuse and bad equipment on the part of external power source.</li> <li>• Faulty lamp</li> <li>• Faulty printed circuit board(PCB)</li> <li>• Faulty line in GUN</li> <li>• Faulty in high-voltage generation part</li> <li>• Faulty trigger switch</li> </ul>	<ul style="list-style-type: none"> <li>• Connect the power</li> <li>• Replace</li> <li>• Replace</li> <li>• Replace</li> <li>• Replace</li> <li>• Replace</li> <li>• Replace</li> </ul>
The powder would not be fluidified.	<ul style="list-style-type: none"> <li>• The Fluidizing air hose is not connected or compressed air is not input</li> <li>• Faulty Fluidizing plate</li> <li>• Faulty operation of pressure reduction valve</li> </ul>	<ul style="list-style-type: none"> <li>• Connect after checking</li> <li>• Replace</li> <li>• Replace</li> </ul>
The gauge hands of CONVEYING AIR and DOSING AIR do not move during operation.	<ul style="list-style-type: none"> <li>• Operation mistake: The power switch is not pressed</li> <li>• The trigger is not pulled</li> <li>• Faulty SOLENOID valve</li> <li>• Faulty PCB</li> </ul>	<ul style="list-style-type: none"> <li>• Turn on the power switch</li> <li>• Check while pulling the trigger during operation</li> <li>• Replace</li> </ul>

MALFUNCTION	CAUSE	MEASURE
The powder would not be ejected even after power switch is on and trigger is pulled.	<ul style="list-style-type: none"> <li>Blockage generated in injector, check valve, sleeve in the injector, paint hose or GUN</li> <li>Worn-down sleeve</li> <li>Poor fluidifying operation</li> <li>CONVEYING AIR is not supplied.</li> <li>Faulty air-adjustment valve.</li> <li>Faulty solenoid valve.</li> <li>Faulty PCB.</li> <li>Oil and moisture contained in the compressed air.</li> </ul>	<ul style="list-style-type: none"> <li>Disassemble and clean</li> <li>Replace</li> <li>Replace</li> <li>Check above issues</li> <li>Replace</li> <li>Replace</li> <li>Replace</li> <li>Install an air dehydrator</li> </ul>
Powder is ejected from GUN but with its electrostatic intensity low.	<ul style="list-style-type: none"> <li>High-voltage assembly is low</li> <li>Faulty GUN connector, wire and wire connector</li> <li>Faulty PCB</li> <li>Faulty high-voltage cascade (H-V CASCADE)</li> <li>Faulty Rod holder</li> </ul>	<ul style="list-style-type: none"> <li>Increase the voltage level</li> <li>Replace the faulty part</li> <li>Replace</li> <li>Replace</li> </ul>
Powder ejection and electrostatic intensity is good, but its attach efficiency is poor.	<ul style="list-style-type: none"> <li>Faulty earth of powder object</li> <li>Too much paint on the conveyor hangar and powder object area</li> <li>The high voltage pin caved in</li> </ul>	<ul style="list-style-type: none"> <li>Check the earth state</li> <li>Remove powder from hangar and powder-object area</li> <li>Replace the rod holder</li> </ul>

5. APPENDIX


(P.C.B)WIRING DIAGRAM  
KCI TYPE 201, 203, 204, 206, 207 KCI-201-1 11, 2006






### WIRING DIAGRAM

KCI TYPE 201, 203, 204, 206, 207 KCI-201-1 11. 2006



### PNEUMATIC DIAGRAM

KCI TYPE 201, 203, 204, 206, 207 KCI-201-1 11. 2006






# GUARANTY

- ◆ We here by certificate quality of our products and guarantee quality and after sales service.
- ◆ Our products were manufactured with first class workmanship and designed to be convenience for customer.
- ◆ We guarantee free service for 15 months after products are alienated to customer. In case, defect of products is being caused by us. But, incase, responsibility of breakdown are caused by user, service charge could be claimed.
- ◆ Products : KCI-201, KCI-203, KCI-204, KCI-206, KCI-207, KCI-C-500, KCI-P-603, KCI-R-1500, and equipments of powder coating etc...

Signed by Youn Chung / president

Koryo Coating Machine, Industrial Co., Ltd.  
  
 President BY YOUN CHUNG

Koryo Coating Machine Industrial Co., Ltd.  
 Tel : 82-31-656-8610 Fax : 82-31-655-8694  
 Address : 258-1, Banje-Ri, Wonkok-Myun,  
 Ansung-Si, Kyeonggi-Do, Korea. (456-811)





## GUARANTEE CARD

PRODUCT NAME	ELECTROSTATIC POWDER COATING SPRAYER
MODEL	KCI-201, 203, 204, 206, 207
Serial No.	
PURCHASE DATE	

AGENT	
TEL	- -

## BUYER CARD

NAME	
TEL	- -
ADDRESS	

**Koryo Coating Machine Industrial Co.,Ltd.**





CE (RWTUV) ISO/KS A 9001 KAB-OC-26 ISO/KS A 14001 KAB-EC-14

- ▶ Acquired CE Mark
- ▶ Acquired ISO 9001 Certification
- ▶ Acquired ISO 14001 Certification
- ▶ Patent right for HV-power switching system

## Koryo Coating Machine Industrial Co., Ltd.

Head Office & Factory : 258-1, Banje-Ri, Wonkok-Myun, Anseong-Si, Kyeonggi-Do, Korea(456-811)  
TEL. (82-31) 656-8610 / FAX. (82-31) 655-8694

China, Shanghai Factory : #55 Hengxiangload, Waigantown, Jiadingqu, Shanghai, China, 201806  
TEL. 86-21-6957-5112 / FAX. 86-21-6957-5110

E-Mail: [kci@kcispray.com](mailto:kci@kcispray.com) <http://www.kcispray.com>